


Flow Scale WP - 1



Purpose:

Libra Scale is automatic weight and recording for flowable materials with weight batches in loose, dusty and grainy form.

Functions:

- total flow and weight measurement and recording,
- the possibility of dispensing a certain amount of material,
- material flow definition,
- communication via the RS-485 (MODBUS RTU or PROFIBUS),

Technical parameters:

- accuracy class 1 - 3 %
- flow do 80 t/h
- temperature range -5°C do + 40°C
- dimensions h x a x b 500 x 450 x 300

